

# COOL-LITE TESTER

No. 9046 - used for candling eggs

## Instructions

Hold light up to the large end of the egg in a dark room. Use to check progress of development. After 10 days check for infertility (entire egg will glow). Remove infertile eggs from the incubator to provide more room for hatching chicks. Two to three days before the projected hatch date approximately  $\frac{1}{3}$  of the egg should show an air pocket as indicated in the photo.



G.Q.F. Mfg Co., P.O. Box 1552, Savannah, GA. 31402